### Order #XXXXX SYM-404 Portable Counter

#### Qty. Description ltem

- 17.25"h aluminum Leg (lower) 2 ---
- 18.5"h aluminum Leg (upper) 2
- 36.5"h aluminum Leg (middle) 1
- 43"w x 21.5"d Counter Base 1
- 17.95"w x 17.92"d Counter Shelf 1
- 43"w x 21.5"d Counter Top 1

#### Steps:

Note: Assemble counter upside-down.

- 1) Attach upper legs to underside of Counter Top. Twist to tighten.
- 2) Connect lower Legs through Counter Shelf to upper Legs, as shown.
- 3) Attach middle leg to underside of Counter Top. Twist to tighten. Note: Holes for standoff graphic should face front of assembly.

Clamp


Clamp


Velcro

- 4) Place Counter Base over lower & middle Legs & secure with wing nuts.
- 5) Turn counter unit over & attach Graphic to middle leg, using Clamps w/ Velcro.


### Assemble unit upside-down.

© 2024





# **SETUP INSTRUCTIONS**



When assembled



**Order #XXXXX** General Information


## **General Setup Instructions**

© 2024


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

## Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.



Part Identification - Numbering



Engaged Lock

## Disassembly

- For loss prevention, keep all knobs & connectors attached to extrusions during disassembly.








### DO NOT USE POWER TOOLS

ALL CONNECTIONS MUST **BE TIGHTLY SECURED** 



© 2024

## Top View of Each Level



Setup Hardware